

Corrections and Amendments

This page will be updated as corrections to the 2004/05 Annual Report come to light.

1. **Page 35 Camden.**

Scheme photographs 5 and 6 are incorrect as they do not show the streets indicated in the text. The **correct** photographs are shown below.



▲ **Scheme Photo 5**

Scheme Code: BS\LCN\CAM.07

Link Number: 28

Location: Royal College St

Description: Re-surfacing and upgrades.

Cost: £57 000



▲ **Scheme Photo 6**

Scheme Code: BS\LCN\CAM.08

Link Number: 28

Location: St. Pancras Way

Description: Re-surfacing and upgrades.

Cost: £48 000